



## State of Vermont

Department of Fish and Wildlife  
Department of Forests, Parks and Recreation  
Department of Environmental Conservation  
State Geologist  
RELAY SERVICE FOR THE HEARING IMPAIRED  
1-800-253-0191 TDD>Voice  
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES  
Department of Environmental Conservation

Waste Management Division  
103 South Main Street / West Office  
Waterbury, VT 05671-0404  
(802)241-3888  
FAX (802)241-3296

October 9, 1996

Mary Dwyer  
35 Middlewood Road  
Williston, VT 05495

RE: Site Management Activity Completed at the Dwyer residence in Williston (Site #95-1830)

Dear Ms. Dwyer:

The Sites Management Section (SMS) has received verbal notification that the soil vapor extraction system at the above referenced site has been dismantled. Therefore, the SMS has determined that no further remedial action is necessary at this site in response to the initial fuel oil spill of approximately 200 gallons which occurred in February, 1995.

This determination was based on the following information:

1. The soil vapor extraction system which was installed following the 200 gallon fuel oil release from an above ground storage tank, has effectively removed petroleum vapors from the subsurface. This is evidenced by the soil gas sampling performed on June 20, 1996 which indicated all BTEX vapor concentrations to be non-detect. The system was shut down and dismantled on September 25, 1996.
2. Groundwater was not impacted at the site. One vapor well installed to the depth of groundwater was sampled on four different occasions and has never shown evidence of any petroleum contamination.
3. Any residual contamination which may remain in the subsurface at the site poses little to no risk to sensitive receptors in the vicinity of the site.

Based on the results of the investigation, the site has been assigned a Site Management Activity Completed (SMAC) designation. Sites which the Waste Management Division have determined require no further management are given a SMAC designation. The designation does not release you from any past or future liability which may arise from the petroleum contamination which originated from the 200 gallon above ground storage tank fuel oil spill at

your residence. The SMAC designation does mean that the SMS isn't requiring any additional work be performed at this site in response to the initial contamination.

Please feel free to contact either me or Chuck Schwer with any further questions or comments you may have.

Sincerely,

A handwritten signature in black ink, appearing to read "George Desch", written over a horizontal line.

George Desch, Chief  
Sites Management Section

c: Blaise Schroeder, Allstate  
Bill Norland

lp/sites/951830/smac